RONJA

Testing 2 Twisters with strong enough power supply

Length virtually unlimited. Must be shielded. Copper stubs not necessary.



520mA @12V regulated power supply