Measuring lens transmitter gain

RONJA



Ul = voltage measured in the hot spot
Us = voltage measured in center of inner surface of the lens
l,s = distance between photodiode and apparent location of LED's crystal