
Ronja Mundaka LNA
TITLE
FILE: Released under GFDL
REVISION: 20090314
PAGE 1 OF 1
DRAWN BY: Clock
Partition not connected to lid
Lid soldered to the partition
Protective cage to prevent evanescent wave interference from the hole
Looking on the label side
BFR91A
CONN1
CONN2
Vbe protection
Ambient